

FIG.1




FIG. 7

Receive Request For Increased Performance Level

<u> 1</u>310

Vary At Least One Overclocking Parameter To Test At Least One Set Of Overclocking Parameters


(315

Apply A Graphical Stress Test To Each New Set Of Overclocking Parameters


320

Determine Maximum Safe Overclocking Parameters That Satisfy Stress Test


FIG. 3



FI 6.4



FI6.5



620




FIG. 8